

4/14/2008

PACKAGE RELIABILITY REPORT FOR

DS1923, Batangas Assembly, RoHS Compliant, No BCB in Streets

Maxim Integrated Products

4401 South Beltwood Parkway Dallas, TX 75244-3292

Prepared by:

Ken Wendel

Ken Wendel Director, Reliability Engineering Maxim Integrated Products 4401 South Beltwood Pkwy. Dallas, TX 75244-3292 Email : ken.wendel@maxim-ic.com ph: 972-371-3726 fax: 972-371-6016 mbl: 214-435-6610

Conclusion:

The following qualification successfully meets the quality and reliability standards required of all Maxim packages:

DS1923, Batangas Assembly, RoHS Compliant, No BCB in Streets

In addition, Maxim's continuous reliability monitor program ensures that all outgoing product will continue to meet Maxim's quality and reliability standards. The current status of the reliability monitor program can be viewed at http://www.maxim-ic.com/TechSupport /dsreliability.html.

Package Description:

A description of this assembly can be found in the product data sheet. You can find the product data sheet at http://dbserv.maxim-ic.com/l_datasheet3.cfm.

Note: Due to the nature of the construction on this assembly, no operating life data is collected. Please see respective product report(s).

The reliability data follows. Some of the data in this report may be generic. At the start of this data is a description of the assembly vehicle used to generate this reliability data. The next section is the detailed reliability data for each stress. If there are additional assemblies used as part of this report, a description of each will follow which includes the respective reliability data for that assembly. Where appropriate, preconditioning is performed before all stresses and the bond crater test unless otherwise noted. The reliability data section includes the latest data available.

Assembly Information: Assembly Site: **Batangas Assembly** Pin Count: 2 Package Type: Puk Can F50 Insert Mold Bump Humidity w-SMT Crystal (RoHS) Body Size: 68 Mold Compound: FP4527, Henkel/Loctite Underfill Epoxy Lead Frame: PCB: FR4 Lead Finish: High Pb Ball (95/5) Die Attach: Underfill FP4527, Dexter Hysol Underfill Epoxy (Blue) Bond Wire / Size: NA / NA UL 94-V0 Flammability: Moisture Sensitivity: NA Date Code Range: 0739 to 0804 VEHICLE: DS1923 **DATE CODE: 0739** LOT NUMBER: MG360684-BATG3A STORAGE LIFE DESCRIPTION CONDITION READPOINT QTY FAILS FA# STORAGE LIFE 85 C 1000 HRS 77 0 Total: 0 UNBIASED MOISTURE RESISTANCE QTY FAILS DESCRIPTION CONDITION READPOINT FA# MOISTURE SOAK 60C/90% R.H. 1000 HRS 77 0 Total: 0 **DATE CODE: 0741** LOT NUMBER: MG360685-BATG4 VEHICLE: DS1923 STORAGE LIFE DESCRIPTION CONDITION READPOINT QTY FAILS FA# STORAGE LIFE 85 C 1000 HRS 77 0 0 Total:

| UNBIASED MOISTURE | RESISTANCE | | | | | | |
|------------------------|---------------|----------------|-----------|-----------|-----|-------|-----|
| DESCRIPTION | CONDITIC | CONDITION | | READPOINT | | FAILS | FA# |
| MOISTURE SOAK | 60C/90% F | 60C/90% R.H. | | 1000 HRS | | 0 | |
| | | | | Total: | | 0 | |
| DATE CODE: 0741 | LOT NUMBER: M | G360686-BATG4A | VEHICLE: | DS1923 | | | |
| STORAGE LIFE | | | | | | | |
| DESCRIPTION | CONDITION | | READPOINT | | QTY | FAILS | FA# |
| STORAGE LIFE | 85 C | | 100 | 00 HRS | 77 | 0 | |
| | | | | Total: | | 0 | |
| UNBIASED MOISTURE | ERESISTANCE | | | | | | |
| DESCRIPTION | CONDITION | | READPOINT | | QTY | FAILS | FA# |
| MOISTURE SOAK | 60C/90% R.H. | | 1000 HRS | | 77 | 0 | |
| | | | | Total: | | 0 | |
| DATE CODE: 0803 | LOT NUMBER: M | G361894-QAL1 | VEHICLE: | DS1923 | | | |
| TEMPERATURE CYCL | E | | | | | | |
| DESCRIPTION | CONDITIC | CONDITION | | READPOINT | | FAILS | FA# |
| TEMP CYCLE | -40 TO 85 | C | 150 | 00 CYS | 77 | 0 | |
| | | | | Total: | | 0 | |
| DATE CODE: 0803 | LOT NUMBER: M | G361895-QAL1 | VEHICLE: | DS1923 | | | |
| TEMPERATURE CYCL | E | | | | | | |
| DESCRIPTION | CONDITIC | CONDITION | | READPOINT | | FAILS | FA# |
| TEMP CYCLE | -40 TO 850 | C | 150 | 00 CYS | 77 | 0 | |
| | | | | Total: | | 0 | |
| DATE CODE: 0804 | LOT NUMBER: M | G361896-QAL1 | VEHICLE: | DS1923 | | | |
| TEMPERATURE CYCL | .E | | | | | | |
| DESCRIPTION | CONDITION | | READPOINT | | QTY | FAILS | FA# |
| TEMP CYCLE | -40 TO 850 | -40 TO 85C | | 1500 CYS | | 0 | |
| | | | | Total: | | 0 | |